2017-18

THIRD PARTY INSPECTION REPORT

Name of the Client: **Asst.Executive Engineer**, T.Dasarahalli Sub Division, BBMP, Bangalore.

Agency: **Technical Manager(West),** KRIDL, Bangalore.

Name of the Work: Improvements to road & drains Siddeshwara layout in Bagalagunte in Ward No.14, T.Dasarahalli subdivision, BBMP, Bangalore.

3rd Party Inspection Consultants

CIVIL XPERTS

CONSULTANTS & TESTING CENTER

NABL Accrediated As Per ISO : 17025 - 2005

ISO 9001 : 2008

#174, Sri Ranga Complex, Amruth Nagara Main Road, New Bank Colony, Konanakunte, Bangalore - 560062 | Mob : +91 97429 59595

Ph : 080 26322565 |e-mail : civilexpertsltd@gmail.com

CIVIL XPERTS
ISO 9001:2008
CONSULTANTS & TESTING CENTER

174, Sri Ranga Complex
Amrutha Nagar Main Road
New Bank Colony, Konanakunte
Bangalore - 560 062.
Mobile : +91 97429 59595
Tele/Fax : 080-2632 2565
E-mail : civilexpertsltd@gmail.com
URL : www.civilexperts.in

NABL ACCREDITED AS PER ISO/IEC 17025:2005

Name of Work : Improvements to road & drains Siddeshwara layout in Bagalagunte in Ward No.14, T.Dasarahalli subdivision, BBMP, Bangalore.

Name of Client	:	**Asst.Executive Engineer,** T.Dasarahalli Sub Division , BBMP, Bangalore.
Contractor/Agency	:	**Technical Manager(West),** KRIDL,
Total Cost	:	Rs.19.95 Lakhs
Date of Inspection	:	28.06.2017
Status of Bill	:	1st & Final Bill
In the Presence of	:	(a) **Assitant Engineer (W. No. 14),** BBMP, Bangalore.
	:	(b) **Mr. Mohan G.** Senior Engineer M/s Civil Experts Consultants, Bangalore.

3rd Party Compliance Report

Sl.No	Description of the Item		Comments / observations
1	Earthwork excavation by manual means in ordinary soil.....	:	Work done up to the billed quantity and Quality is satisfactory
2	Compaction of Original ground with maximum 6 passes 8to 10 tonnes power roller	:	Work done up to the billed quantity and Quality is satisfactory
3	Construction og granulr sub base with coarse graded material	:	Work done up to the billed quantity and Quality is satisfactory
4	providing, laying, spreading and compacting graded stone aggregate in wet mix macadam.....	:	Work done up to the billed quantity and Quality is satisfactory
5	Cleaning existing black topped surface with brooms, soft brushes and finaly dusting with old gunny bags.....	:	Work done up to the billed quantity and Quality is satisfactory

For Civil Experts Consultants

Authorised Signatory

CIVIL XPERTS
ISO 9001:2008
CONSULTANTS & TESTING CENTER

174, Sri Ranga Complex
Amrutha Nagar Main Road
New Bank Colony, Konanakunte
Bangalore - 560 062.
Mobile : +91 97429 59595
Tele/Fax : 080-2632 2565
E-mail : civilexpertsltd@gmail.com
URL : www.civilexperts.in

NABL ACCREDITED AS PER ISO/IEC 17025:2005

6	Providing applying primer coat with bitumen emulsion on preapred surface.....	:	Work done up to the billed quantity and Quality is satisfactory
7	Providing and laying bituminous macadam on prepared surface with crushed course aggregate as per design mix.....	:	Work done up to the billed quantity and Quality is satisfactory
8	providing applying tack coat with bitumen emulsion.....	:	Work done up to the billed quantity and Quality is satisfactory
9	Providing and laying bituminous concrete 40mm thick grading-2 using VG30 bitumen	:	Work done up to the billed quantity and Quality is satisfactory
10	Road marking with hot applied thermoplastic compound with reflectrising glass beads on bituminous surface.....	:	Work done up to the billed quantity and Quality is satisfactory

For Civil Experts Consultants

Authorised Signatory

Authorised Signatory